



## PROJECT: PRIVATBRAUEREI HIRT GMBH



### Project information

City: 9322 Micheldorf / Austria

---

# PROJECT DETAILS

## Project images











## Products used



### **8841 LED bollard**

The 8841 LED product range scores with a characteristically high-profile appearance and a diversity of luminaire versions. Various wide light distributions and different luminous flux packages provide maximum visual comfort and guarantee perfect illumination, enabling large spacing between the bollards.

---



### **Amatris LED downlight ceiling cutout Ø 120/200 mm**

In terms of luminaire luminous flux, the compact Amatris recessed LED downlight with 1400 lm and 1900 lm is one of the big boys. With its reduced bezel ring and white reflector, the luminaire can be integrated into almost all surroundings.

---



### **Inplana LED downlight ceiling cutout Ø 215/300/425 mm**

Inplana and Onplana LED downlights are the optimum lighting solution for nearly all office applications. Thanks to their modern, minimalist design these flat downlights blend harmoniously into all styles of architecture and emit planar, glare-free light when mounted on walls and ceilings.

---



### **Polaron IQ LED surface-mounted luminaire**

The basis element of the Polaron IQ LED family is a filigree, round light profile supplying maximum planning flexibility: Its diversity enables countless combinations in the series – meaning that light and luminaire design can be perfectly modified to the application. The custom-designed luminaire is installed without any effort thanks to a clever fixing concept.

---



### **Polaron IQ LED suspended luminaire**



### **Acuro LED wall surface-mounted luminaire**

Glare-free, harmonious light in bathrooms is a real challenge due to reflective surfaces. The new TRILUX Acuro wall-mounted mirror luminaire meets this demand for light quality with ease and also features both reliable protection against splashwater and an attractive design. Equipped with LED technology, the luminaires also benefit from a long service life and almost no maintenance.

---